#### RISA TECHNOLOGIES WEBINAR

# Design of Stiffeners and Non-Concentric Brace Connections

Matt Brown, S.E.



#### **Integrated Programs**

- RISAFloor v7.0.2
- RISA-3D v11.0.2
- RISAConnection 3.0.1



#### Referenced Codes

# AISC 360-10 (14th Edition Manual)



Image courtesy of AISC.org



#### Referenced Codes

# **AISC Design Guide 13**





Image courtesy of AISC.org




#### **Moment Arm**






#### MOMENT CONNECTIONS

## Flange Bearing






# Flange Bearing





# Flange Bearing

A. CJP weld






Column Flange Local Bending





Column Web Local Yielding





Column Web Crippling






Column Web Buckling






Panel Zone Shear Failure





## Flange Stiffeners


- Flange Buckling
- Web Yielding
- Web Crippling
- Web Buckling






#### **Web Stiffeners**

Panel Zone Shear






#### Plate Aspect Ratio






# **Plate Aspect Ratio**






## **Non-Concentric Workpoints**








## **Non-Concentric Workpoints**








# **Physical Geometry**






## **Physical Geometry**





# **Physical Geometry**





#### **Questions?**

Please let us know if you have questions.

We will answer as many questions as time permits during the webinar.

Once the webinar is closed, we will post all Q&A's, as well as any supporting materials to our website:

www.risa.com

For further information, contact us at: info@risa.com

#### THANK YOU FOR ATTENDING